

# HEXPRO®

## PRESSURE/TORQUE CONVERSION CHART

PSI	BAR	FT. LBS.	Nm
1000	69	2577	3494
1200	303	3092	4193
1400	97	3608	4891
1600	110	4123	5590
1800	124	4693	6363
2000	138	5262	7134
2200	152	5845	7925
2400	165	6428	8715
2600	179	7011	9506
2800	193	7594	10296
3000	207	8177	11087
3200	221	8757	11873
3400	234	9337	12659
3600	248	9916	13444
3800	262	10496	14231
4000	276	11076	15017
4200	290	11666	15817
4400	303	12255	16616
4600	317	12845	17415
4800	331	13434	18214
5000	345	14024	19014
5200	359	14618	19819
5400	372	15212	20625
5600	386	15806	21430
5800	400	16400	22235
6000	414	16994	23041
6200	427	17591	23850
6400	441	18187	24658
6600	455	18784	25468
6800	469	19380	26276
7000	483	19977	27085
7200	496	20569	27888
7400	510	21161	28690
7600	524	21752	29492
7800	538	22344	30294
8000	552	22936	31097
8200	565	23528	31900
8400	579	24120	32702
8600	593	24712	33505
8800	607	25304	34308
9000	621	25896	35110
9200	634	26489	35914
9400	648	27082	36718
9600	662	27675	37522
9800	676	28268	38326
10000	689	28861	39130



**HexPRO 30**

Ontdek meer bij:  
**AnMa - TECH B.V.**



**MAXDRV**

**Stephan Dahlmann**

Mechanik und Antriebstechnik GmbH



**HEXPRO**

