

PRESSURE/TORQUE CONVERSION CHART

.7MD

Pressure in PSI	<i>Pressure in BAR</i>	FT. LBS.	<i>Nm</i>
1000	69	64	87
1200	83	79	107
1400	97	95	129
1600	110	110	149
1800	124	126	171
2000	138	140	190
2200	152	156	212
2400	165	172	233
2600	179	189	256
2800	193	205	278
3000	207	221	300
3200	221	237	321
3400	234	253	343
3600	248	270	366
3800	262	287	389
4000	276	302	409
4200	290	319	433
4400	303	335	454
4600	317	352	477
4800	331	368	499
5000	345	384	521
5200	359	401	544
5400	372	417	565
5600	386	434	588
5800	400	450	610
6000	414	466	632
6200	427	483	655
6400	441	499	677
6600	455	515	698
6800	469	531	720
7000	483	548	743
7200	496	564	765
7400	510	581	788
7600	524	598	811
7800	538	614	832
8000	552	631	856
8200	565	647	877
8400	579	664	900
8600	593	679	921
8800	607	695	942
9000	621	711	964
9200	634	728	987
9400	648	745	1010
9600	662	761	1032
9800	676	778	1055
10000	689	793	1075